

Report No. : 1408060013

Tamper Evidence Report as per ISO 17712:2013

Date of issue : August 07, 2014

Description of Samples : Security Seals


Name & Address of the Client : Pack Seals Industries,
102, 1st Floor, Utkarsh Co-Op Housing Society Ltd.,
Rammandir Road, Near Anandrao Pawar School,
Babhai Naka, Borivali (W),
Mumbai-400092.

Reference : TRM Dt. 31.07.2014

Done At : On Site

Details:

- The following seals were tested for Tamper Evidence.



- These seals were then put on the door lock on a container.



(Authorized Signatory)

- Various methods were opted to try to break the seal.
 - i. Using a Drill Machine



- ii. Using a Hammer & Chisel



- iii. Using a Hacksaw Blade



(Authorized Signatory)

Observations & Conclusion:

- The seals were then inspected for any kind of breakage or tamper evidence.
- The impact & impression of tampering was clearly visible on the face of the seals.
- In spite of sufficient effort the seals remained intact.
- No distortion or breakage was observed in the seals.



*****END OF REPORT*****

(Authorized Signatory)

THIS INSPECTION REPORT IS BASED ON OUR ACTUAL FINDINGS. THE INSPECTION WAS DONE TO THE BEST OF OUR KNOWLEDGE AND ABILITY AND WITH DUE CARE. THE FINDINGS ARE VALID AS FOR TIME AND PLACE OF INSPECTION.